



Common Blind Spots in Ground Investigation, Design, Construction, Performance Monitoring and Feedbacks in Geotechnical Engineering

Ir. Liew Shaw Shong

G&P Geotechnics Sdn Bhd, Kuala Lumpur, Malaysia




Mission Statement

- Site Investigation
 - Planning, Execution & Interpretation
- Forensic Investigation
 - Stability of Piled Supported Retaining Wall
 - Embankment Distress (Strain Incompatibility)
 - Abutment Distress due to Piled Embankment Failure
 - Unreliable Facing Capacity of Soil Nailed Slope
 - Illusive End Bearing Pile Capacity
 - Non-linearity Elasto-Plastic & Hysteresis Phenomena of Pile-Soil Interaction Performance


Site Investigation

- List CEO and key management by name.
- Include previous accomplishments to show that these are people with a record of success.
- Summarize number of years of experience in this field.




Lessons Learnt on Stability of a Piled Retaining Wall in Weak Soils

Ir. Liew Shaw-Shong




Content

- ⊕ Chronological events
- ⊕ Distress conditions of wall
- ⊕ Desk study & subsurface conditions
- ⊕ Forensic investigation (Geotechnical & Structural assessments)
- ⊕ Probable Causations
- ⊕ Remedial Solution
- ⊕ Conclusion





Chronological events

- ✚ First SI : Jan 2005 (Within project site)
- ✚ Second SI : May 2005 (at wall area)
- ✚ Wall Distress : Feb 2006 (After prolonged rain)
- ✚ Forensic Investigation : Feb to Mar 2006




Tension Crack & Wall Distresses







Overall View of Site






Cross Section of Wall






Weephole Drains






Erosion by Weephole Discharge







Erosion of Wall Base







Aerial View (Pre-development)







Site Topography & SI Works







Previous 2-Stage Boreholes






Forensic Boreholes





Vane Shear Test Strength Profile

Interpretation of Vane Shear Test Results




RL38.34m
(Possible Slip Surface)


Peak strength and remoulded strength are obtained from vane shear test results.

Peak Strength adopted in analysis, $S_u=25$ kPa

Mesri Line = $0.22\sigma'_v$
Undrained shear strength profile of normally consolidated fine soils




Stability Assessments





FOS Adequacy			
GWT	Overturning	Sliding	Global Stability
RL45m	✓ 2.9 > 2.0	✗ 0.97 < 1.0 (Failure)	✗ 1.13/1.17
RL42.5m	✓ 3.7 > 2.0	✗ 1.34 < 1.5	✓ / ✗ 1.19/1.25
RL40.4m	✓ 3.8 > 2.0	✗ 1.5	✓ / ✗ 1.16/1.24

Bearing Capacity is never a concern as pile foundation is designed to take the vertical loading of wall



More prominent in effective stress analysis, but less for total stress analysis






Pile Integrity Testing




**6 PIT : Discontinuity
detected at depths from
1m to 4m below pile top**




Pile Structural Assessments

- ✚ Rankine Pressure
- ✚ Brom's Lateral Pile Capacity:
 - ▣ Fixed Head : 32kN/pile (Likely the case)
 - ▣ Free Head : 20kN/pile
- ✚ Ultimate lateral pile capacity reached when $RL42.5m < GWT < RL45m$




Probable Causes of Wall Distress

- ⊕ Potential perched water regime in natural valley terrain after raining
- ⊕ Rise of groundwater increases the lateral force on wall
- ⊕ Inadequate lateral pile resistance
- ⊕ Reduction of effective soil strength due to reduction of vertical stress as wall loading carried by piles





Remedial Solution

- ❖ Soil Replacement for upper weak soil
- ❖ Overcut existing piles below new wall base
- ❖ Construct stabilising berm in front of new wall
- ❖ Provide subsoil drainage behind wall to control rise of groundwater seepage



Remedial Solution





Conclusion

- ⊕ Potential perched water regime in natural valley terrain after raining
- ⊕ Rise of groundwater (inefficient sub-terrain drainage) increases the lateral force on wall
- ⊕ Inadequate lateral pile resistance
- ⊕ Reduction of effective soil strength due to reduction of vertical stress as wall loading carried by piles
- ⊕ Slender vertical piles not suitable for supporting wall on weak & compressible soils (Poor lateral resistance)
- ⊕ Remedial works : Soil Replacement + Subsoil drainage + Stabilising berm
- ⊕ Solution : Raked piles in combination of vertical piles (Serviceability limit state)

Role of Extendible Basal Reinforcement for Embankment Construction Over Soft Soils

- ▶ Introduction
- ▶ Problem Statements & Distress
- ▶ Back Analysis
- ▶ Discussions
- ▶ Conclusions
- ▶ Recommendations



Introduction

- Embankment → Raised fill platform with side slopes to support structure and infrastructure developments.
- Stage construction + additional reinforcement → Ensure acceptable side slope stability
- Basal reinforcement → To minimise spreading failure of compacted embankment fill over weak supporting subsoils

Basal Reinforcement

- Shall be designed in accordance with BS8006.
- Consideration → Strain compatibility between embankment fill and basal reinforcement system.
- Tensile strain in basal reinforcement shall be controlled to avoid cracking in embankment fill.

Basal Reinforcement

- If the embankment is strained to excessive tensile crack, the embankment fill material strength is doubtful.
- Thus, case study of an instrumented embankment construction with extendible basal reinforcement have been used.
- This may call for a review of the permissible strain of extendible basal reinforcement with brittle compacted fill.

Problem Statement & Distresses

▶ Problem Statements


- ▶ Embankment Fill over Soft Deposits
- ▶ PVD with Staged Construction
- ▶ Basal Reinforcement for Temporary Embankment Stability
- ▶ BS8006
- ▶ Strain Incompatibility

▶ Distresses

- ▶ Longitudinal flexural cracks on embankment surface



Embankment Distresses




Embankment Distresses



Embankment Distresses

Alligator cracks
observed on site.




Embankment Distresses

**1 m surcharge removal
after distresses observed**



Embankment Distresses



**Cracks found after 1 m
surcharge removal.**



Embankment Distresses




Excavation on cracks found after 1m surcharge removal




Instrumentation Layout

Instrumentation Layout
Plan at Distresses area




Instrumentation Results

Fill Thickness and Settlement of Embankment with time monitoring by SG580




Instrumentation Results

Inclinometer I6 Monitoring Results



Finite Element Model



Finite Element Model

Back analysis to match lateral deformation and settlement profiles.

Two cases were modelled for back analysis:-


Case 1: Ultimate strength (600kN/m) mobilized at 10%

Case 2: Ultimate strength (140kN/m) mobilized at 1%




Finite Element Model

Comparison of Back Analysed Settlement Trend With Actual Measurement (Case I)



Finite Element Model


Comparison of Lateral Displacement Profile (Case I)



Summary of Back Analyses

Stage	Tensile Stiffness	Mobilised Tensile Load / Tensile Strain	Maximum Lateral Deflection at Edge of Embankment (mm)
S1	Case 1	40.6kN/m / 0.68%	267
	Case 2	65.9kN/m / 0.47%	(173)
R1	Case 1	41.8kN/m / 0.70%	295
	Case 2	67.4kN/m / 0.48%	(180)
S2	Case 1	64.6kN/m / 1.08%	400
	Case 2	106.8kN/m / 0.76%	(253)
R2	Case 1	67.4kN/m / 1.12%	425
	Case 2	110.3kN/m / 0.79%	(265)

Probable Mechanism



Discussion

- ▶ Strain incompatibility between basal reinforcement and embankment fill could potentially cause embankment cracking.
- ▶ Average tensile strain of underlying weak subsoils is more than max. tensile strain in basal reinforcement.
- ▶ Results of back-analysis → indicated mobilised tensile strength and strain < conventional assumed values for LEA stability analysis.



Conclusion

- ▶ Longitudinal cracks → Outcome of plastic straining of upper weak alluvium within the underlying subsoil below the embankment loading.
- ▶ Review on current design practice by arbitrarily adopting unrealistic high mobilised strength is needed.
- ▶ Wishful high tensile strain assumed in LEA can lead to misrepresentation on safety margin of embankment.



Recommendations

- ▶ Counterweight berm was proposed to solve the strain incompatibility between basal reinforcement and the subsoil.
- ▶ Instrument on basal reinforcement to reveal the distribution profile and performance of installed basal reinforcement.




Case 2: Case study on Piled Supported Embankment Failure



Site Conditions

- ▶ Embankment (maximum 5.4m high) with Piles & Ground Improvements
 - ▶ Ch3328 to Ch3375 (Top 10m soft Clay, $S_u = 10\sim 15\text{kPa}$)
- ▶ Distressed Abutment
 - ▶ Abutment A @ Ch3266 (Top 15m soft Clay, $S_u = 13\sim 18\text{kPa}$)
 - ▶ Abutment B @ Ch3328 (Top 9m soft Clay, $S_u = 7\sim 12\text{kPa}$)



Findings from Site Inspection

- ▶ **Piles & slab** of piled embankment suffered structural distress
- ▶ Settlement of **0.4 to 1.0m** beneath piled embankment due to consolidation of subsoils under the working filled platform.
- ▶ Bearing distortions confirmed : Bridge deck moving from Abutment B towards Abutment A




Site Inspection Findings

- ▶ Piled Embankment 30m from Abutment B shown structural distress



Site Inspections Findings

- ▶ Piles of Piled Embankment has shown flexural cracks



Site Inspections Findings

- ▶ Damaged piled embankment slab damaged & 100mm gap at slab joint



Site Inspections Findings

- ▶ Settlement of 0.4 to 1.0m under the Piled Embankment



Site Inspections Findings

- ▶ Bearing distortion at Pier P2




Site Inspections Findings


- ▶ Bearing distortion at Pier PI



- P_A : Active Earth Pressure
- P_1 : Action/Reaction Force between Piled Embankment Slab & Abutment
- P_2 : Ultimate Lateral Pile Group Capacity of Embankment Piles
- P_3 : Mobilised Thrust on Stability Soil Mass with Corresponding FOS




- Settlement Markers (LDC) : 28 May -31 Jul 2005
- Displacement Markers (by LDC) : 02 Mar – 18 Jun 2006
- Displacement Markers (by G&P) : 25 Apr – 7 May 2007



P_A : Active Earth Pressure
 P_1 : Action/Reaction Force between Piled Embankment Slab & Abutment
 P_2 : Ultimate Lateral Pile Group Capacity of Embankment Piles
 P_3 : Mobilised Thrust on Stability Soil Mass with Corresponding FOS

- ← Movement Direction
- ↻ Clockwise Rotation
- ↻ Anti-Clockwise Rotation
- ⊛ Developing Pile Plastic Hinge
- ⊛ Bearing Distortion
- FOS** (Factor of Safety)
- Tension Cracks
- PVD + EVD Area




Investigation Findings

- ▶ **Embankment (5.4m high)**
 - ▶ Ch3375 : **FOS \cong 1.0** at Embankment on Ground Treatments
 - ▶ Causation : Inadequate FOS => Embankment instability exerting lateral stress to Piled Embankment on free standing piles due to subsoil consolidation
- ▶ **Distressed Abutment**
 - ▶ Abutment B : Laterally pushed by **unstable embankment** behind piled embankment
 - ▶ Abutment A & Two piers : Affected by lateral thrust from Abutment B (**No observable distresses** at the abutment pile foundation after exposure of piles)



Abutment Remedial Design

- ▶ **Abutment Distress (Ch3266 to Ch3328)**
 - ▶ Remedial proposal :



Conclusions

- ▶ **Weak post-treatment soil strength** unable to support embankment
- ▶ **Creep movement** of weak subsoil beneath embankment coupled with embankment instability due to **low FOS**
- ▶ Further **consolidation** of weak overburden soil, the lateral resistance of piled embankment in free standing pile conditions is weaken
- ▶ Monitored bridge displacement confirmed pattern of lateral movement of entire bridge & piled embankment
- ▶ Structural damage on embankment piles was expected as structural threshold has reached
- ▶ Use of **residual strength** is needed for rectifying failed embankment



Recommendations

- ▶ Construct new embankment slab at least **1m** below the failed slab to prevent further consolidation settlement
- ▶ Extend piled embankment for embankment fill **higher than 2m** & provide isolation gap at the slab/abutment interfaces
- ▶ Use of **higher strength RC pile** for embankment piles
- ▶ Use of geotextile reinforcement to isolate embankment fill from both abutments to **reduce direct lateral earth pressure** on abutments



Unreliable Facing Capacity of Soil Nailed Slope

- With intention of minimized earthwork cutting forming any platform, soil nailed slope profile is normally steep
- Facing capacity has remarkable effect on Internal Stability of steep soil nailed slope
- Volumetric swelling & shrinkage of soils with moisture variation are realistic observation
- Moisture depletion after covering with shotcrete surface results in volumetric shrinkage of slope soil face leaving air gap with separation of contact with shotcrete
- Mobilisation of face capacity in uncontacted slope surface is unrealistic, thus giving incorrect safety margin of slope stability


Volumetric Shrinkage of Exposed Soil



Gap below Shotcrete Surface with Depleting Moisture



Nail Force Diagram






Case Study 1 : Reduced Empty Pre-bored Jack-in Pile Capacity in Meta-Sedimentary Formation

- Overview of pile installation & Performance
- Subsurface Information
- Contractually Scheduled MLT Results
- Additional MLT Results
- Investigation Findings
- Conclusions & Recommendations

Overview Foundation System

- 400mm RC square pile
- Pre-boring was deployed to
 - Overcome intermittent hard layer
 - Avoid shallow pile penetration
- Jack-in pile installed inside pre-bored hole

Pre-bored Hole Diameter

600mm diameter	500mm diameter	550mm diameter
 <p data-bbox="465 825 629 896">Pre-bored hole</p>	 <p data-bbox="803 815 1128 851">400mm dia. RC Pile</p>	 <p data-bbox="1199 911 1547 1051">Compromised pre-bored hole (Adopted)</p>
<p data-bbox="291 911 658 989">Too large pre-bored hole</p>	<p data-bbox="745 911 1112 989">Too small pre-bored hole</p>	<p data-bbox="1199 911 1547 1051">Compromised pre-bored hole (Adopted)</p>


Void in Pre-bored Hole Annulus



Collapsed Debris in Pre-bored Hole Annulus



Actual Scenario of Installed Piles



MLT Results

Maintained Load Test (MLT)	Pre-bored Diameter (mm)	Pile Penetration below Piling Platform (m)	Max. Jack-in Load at Termination (kN)	Achieved Maximum Test Load (kN)	Pile Top Settlement	
					At Working Load (mm)	At Max. Test Load (mm)
MLT 1	600	9.40	2160	2220 (1.71xWL)	14.0	46.00
MLT 2	500	9.30	2600	2220 (1.71xWL)	23.50	42.00
MLT 3	550	12.50	2860	2600 (2.00xWL)	5.80	21.80
MLT 4	550	9.50	2860	1406 (1.50xWL)	16.50	24.50
MLT 5	550	13.50	2860	1950 (1.50xWL)	8.50	13.00


Jack-in Pile Termination Criteria

- All piles were jacked to 2.2 times pile working load
- Settlement < 5mm during 30 seconds holding period for 2 consecutive times

BUT

- **Max Test Load < Jack-in Load**
- **Non-conforming Piles Settlement Criteria**


Boreholes Information





Photos of Exposed Subsoils





Contractually Scheduled MLT Results
















Additional MLT Results


Additional MLT


- 3 nos additional MLT at various penetration below pre-bored base:
- MLT6 – 0.5m below pre-bored base
- MLT7 – 1.5m below pre-bored base
- MLT8 – 2.0m below pre-bored base

Additional MLT











MLT	Pre-bored Diameter (mm)	Pile Penetration below Piling Platform (m)	Max. Jack-in Load at Termination (kN)	Achieved Maximum Test Load (kN)	Pile Top Settlement	
					At Working Load (mm)	At Max. Test Load (mm)
MLT 1	600	9.40	2160	2220 (1.71xWL)	14.0	46.00
MLT 2	500	9.30	2600	2220 (1.71xWL)	23.50	42.00
MLT 3	550	12.50	2860	2600 (2.00xWL)	5.80	21.80
MLT 4	550	9.50	2860	1406 (1.50xWL)	16.50	24.50
MLT 5	550	13.50	2860	1950 (1.50xWL)	8.50	13.00
MLT 6	550	9.50	2860	1950 (1.50xWL)	15.08	42.38
MLT 7	550	10.50	2860	2400 (1.85xWL)	11.29	41.93
MLT 8	550	11.00	2860	2600 (2.00xWL)	10.30	50.35


Investigation Findings



Analogy of Footing



Bearing Improvement with Toe Confinement



Conclusions & Recommendations

- Pile performance improved with longer pile penetration below pre-bored base
- Existence of pile toe softening due to relaxation of pile tip founding material
- Sufficient pile penetration below pre-bored base is important
- Recommend to seal the pre-bored hole with grout

▶ Rapid pile installation in **incompressible** soft soil induces

- ▶ Vertical heave in shallow depth (relatively less confinement from weight of overburden soils)
 - ▶ Lateral displacement in deeper depth (with soil confinement)
- ▶ Consequences :
- ▶ **Up-heaving soil movement** causes **tensile stress** on pile & toe lift up during driving & downdrag after pore pressure dissipation
 - ▶ **Lateral soil displacement** causes **flexural stress** on pile & pile deviation
 - ▶ Excessive combined tensile and flexural stresses lead to **pile joint dislodgement**
 - ▶ Excessive foundation settlement in post construction (**pile toe uplifting & downdrag settlement**)




Pile Joint Dislodgement

- ▶ Pile joints could be dislodged due to excessive flexural and tensile stresses induced by ground heave and radial soil displacement
- ▶ Detectable using High Strain Dynamic Pile Test (HSDPT)



Mechanism of Pile Heave & Soil Displacement



Case Study - HSDPT

- ▶ Monitoring of pile top settlement during the HSDPT re-strike tests is summarised as below:


Cumulative Pile Top Settlement (mm)	Pile C	Pile A	Pile B	Pile D	Pile E
Upon resting 7-ton hammer on pile top	80	98	125	103	92
At the end of Restriking Test	275	399	497	186	182



Case Study - HSDPT

- ▶ Pile B
- ▶ Initial Blow


One Pile Length (12m) was DETECTED with Major Discontinuity at 'toe' (reflection)



Case Study - HSDPT

- ▶ Pile B
- ▶ Blow No. 4


First Joint Discontinuity closed up after few blows; Two Pile Lengths was revealed with another Major Discontinuity at new 'toe' (reflection)



Case Study - HSDPT

- ▶ Pile B
- ▶ Blow No. 17


Second Major Joint
Discontinuity also
disappeared;
Total of Three Pile
Lengths was observed





Case Study - HSDPT

- ▶ Pile B
- ▶ End of Blow



Minor velocity reflections were observable at first and second pile joints



Pile Heave Monitoring Program



Pile Heave Monitoring Result



Summary

- ▶ **Ground heave & radial soil displacement** due to rapid installation of displacement pile in soft incompressible soft clay can pose serious integrity problem on pile foundation.
- ▶ Solutions :
 - ▶ Use **larger** pile spacing & **reduce rate** of clustered pile installation for adequate time for dissipation of excess pore pressure
 - ▶ Simultaneous pile installation at mirror pile location from **centre outwards** to minimise net lateral displacement, but this improves nothing on ground heave
 - ▶ Stronger **pile structural strength & joint** to withstand tensile & flexural stresses
 - ▶ **Staggered pile installation sequence** or install piles at **alternate** locations
 - ▶ **Restrike all piles with HSDPT** to detect pile integrity if ground or soil heave is observed.



Opportunities

- Identify problems and opportunities.
 - State consumer problems, and define the nature of product/service opportunities that are created by those problems.

Business Concept

- Summarize the key technology, concept, or strategy on which your business is based.

Competition

- Summarize the competition.
- Outline your company's competitive advantage.

Goals and Objectives

- List five-year goals.
- State specific, measurable objectives for achieving your five-year goals.
 - List market-share objectives.
 - List revenue/profitability objectives.

Financial Plan

- Outline a high-level financial plan that defines your financial model and pricing assumptions.
 - This plan should include expected annual sales and profits for the next three years.
 - Use several slides to cover this material appropriately.

Resource Requirements

- List requirements for the following resources:
 - Personnel
 - Technology
 - Finances
 - Distribution
 - Promotion
 - Products
 - Services

Risks and Rewards

- Summarize the risks of the proposed project and how they will be addressed.
- Estimate expected rewards, particularly if you are seeking funding.

Key Issues

- Near term
 - Identify key decisions and issues that need immediate or near-term resolution.
 - State consequences of decision postponement.
- Long term
 - Identify issues needing long-term resolution.
 - State consequences of decision postponement.
- If you are seeking funding, be specific about any issues that require financial resources for resolution.