

Slope Failures in Tropical Residual Soils

Presented by:
Ir. Dr. Gue See Sew
21 April 2005

Highland Tower 1993




Debris Flow 2004



Contents

- Creep Movement of Slopes, Sabah.
- Cut Slope Failure in Skudai, Johor.
- Cut Slope Failure at Gua Musang, Kelantan.
- Cut Slope Failure at Kuala Lumpur.
- Filled Slope Failure at Salak Tinggi.

Creep Movement of Slope, Sabah



Ground Movements

- Damage of road pavement and drains.
- Tension cracks, settlement and lateral movement.
- Investigation of root causes.




Road Settlement

Site Background

- RL1335m to RL1500m.
- Terrain : Undulating/Slope.
- Outcrops: Granitic boulder/ Grey Shale/ Sandstones.
- Deposits of Pinosuk Gravel from Mt. Kinabalu.
- Glaciation & Ancient Mudflow.



Granitic Boulder




Outcrop of Pinosuk
Gravel

SI & Laboratory Testing

- Six Boreholes & Inclinometers
- Six Piezometers (GWT : 1.5~2.5m)
- C.I.U. Tests & Direct Shear Box Tests ($\phi' = 21^\circ$, $c' = 10\text{kPa}$).
- Others Properties : $w_n = 7\%$ to 13% , $\gamma_{\text{bulk}} = 21 \sim 23.7\text{kN/m}^3$
- Normally Consolidated


Shear Strength Test Results



Monitoring Results

- Inclinometers detected slip surface.
- Lateral Movement:
- Direction : $225^{\circ} \sim 250^{\circ}$
- Max. Movement : 140mm (IN-4)
- Rate of Movement : 2~14mm/week
(Max. 21mm/week)

Inclinometer Movement Rate




Engineering Assessment


- Interpreted laboratory shear strength parameters are too high to cause instability.
- Back-analysis shear strength parameters:
 $\phi' = 13^\circ \sim 16^\circ$, $c' = 0 \sim 5 \text{ kPa}$

Findings

- Slip Surface : 6m (higher ground) to 15m (lower ground).
- Movement Direction: almost parallel to road alignment, towards river.
- Back-analysed shear strength < Interpreted laboratory test results.



 Borehole
 (Inclinometer)



Recommendations


- Carry out continuous sampling at shear plane to collect samples for testing.
- Carry out ring shear test or multiple reversal direct shear box test to determine residual strength.

Cut Slope Failure in Johor



Site Background

- RL54m to RL106m.
- Terrain : Slope.
- Geology: Mainly basic intrusive gabbro and intermediate intrusive.
- Two berms cut slope 1V:1.5H.
- Slope collapsed after heavy downpour.



Tension Cracks

Site Observations




Water Seepage

SI and Instrumentations

- SI and instrumentation for failure investigations:
- 4 boreholes within failed mass area.
- 3 inclinometers.
- 3 observation wells and 1 standpipe piezometer.


SI Layout Plan



Instrumentation Results

- IN-1 and IN-2 were sheared off at 10.5m and 12.0m below ground.
- IN-3 sheared off at 2.5m below ground.
- Observation wells were also sheared off.

Interpreted Slip Surfaces



Laboratory Test Results

- CIU test :

- a. Peak strength – $c' = 3.5 \text{ kPa}$, $\phi' = 32^\circ$

- b. Critical state strength – $c' = 3.0 \text{ kPa}$, $\phi' = 29^\circ$

- Direct Shear Box test : (fairly scattered)


- a. Peak strength – $c' = 15.7 \text{ kPa}$, $\phi' = 24^\circ$

- b. Critical state strength – $c' = 5.9 \text{ kPa}$, $\phi' = 20^\circ$

Back-Analysis

- Back-analyses were performed for 2 conditions:
 - a. Slope profile after cutting, before failure. (critical state strength)
 - b. Slope profile after failure. (residual strength)
- The interpreted slip surface and monitored groundwater level is used for back-analysis.

Slope Profile for Back Analysis





Back-Analysis Results

- Back-analyses using PC-Stabl6 and Plaxis.
- Back-analyses results :
 - a. Critical state strength : $c'=0 - 0.5$ kPa, $\phi'=24^\circ - 25.9^\circ$
 - b. Residual strength : $c'=0 - 0.5$ kPa, $\phi'=14.4^\circ - 15^\circ$

Residual Strength

- Comparisons with literature:
 - a. Residual friction angle – Liquid Limit.
 - b. Residual friction angle – Clay size fraction.
- Back analysed residual friction angle are lower as compared to literatures.





Findings and Recommendations

- The investigation deduced that there is a thin layer at the slip surface with low shear strength.
- Boreholes are not able to capture the thin layer and could only be detected by inclinometer.
- Residual shear strength should be used for remedial design works.

Cut Slope Failure at Gua Musang, Kelantan



Site Observations




Site Background

- RL210m to RL330m.
- 7 Upper berms of 1V:1H Cut Slope & 5 Lower berms of 4V:1H Soil Nailed Slope
- Soil Nail = 12m with spacing of 1m(V):1m (H)
- Geology: Shale Facies in Gua Musang Formation which mainly consists of Mudstone & Sandstone
- A massive slope failure occurred before soil nails were installed at the lowest berm.


Geological Mapping

- 'Line Mapping' Method
 - To measure & record discontinuity along the exposed slope face
 - To detect anomalous features
 - Schmidt Rebound Hammer to give indication on weathering condition

Site Observations




Bedding of Cut Slope Day-lighting Towards Main Road




SI & Laboratory Works

- 2 boreholes
- 3 C.I.U. Tests
- 2 Multiple Reversal Direct Shear Box Tests
- Grade IV Material
 - a. Peak strength – $c'=30\text{kPa}$, $\phi'=33^\circ$
 - b. Residual strength – $c'=0\text{kPa}$, $\phi'=33^\circ$
- Grade III Material
 - a. Peak strength – $c'=30\text{kPa}$, $\phi'=39^\circ$
 - b. Residual strength – $c'=0\text{kPa}$, $\phi'=33^\circ$

SI Layout Plan




Slope Profile




Engineering Assessment

Slope Stability Analyses




Limit Equilibrium Method

Slope Stability Analyses




Limit Equilibrium Method


Finite Element Analyses




Finite Element Analyses




Finite Element Analyses




Finite Element Analyses



Finite Element Analyses



Finite Element Analyses



Findings

Possible Causes of Failure

- Steep upper cut slope of 1V:1H.
- Inadequate soil nail length of 12m.
- Day-lighting geological structures of Grade III to V materials at the upper cut slope.
- Progressive failure have leaded to develop of a continuous shear surface.

Cut Slope Failure at Kuala Lumpur



Site Observations



Closed Drain at
Toe of Slope




Site Background

- The cut slope with 6 berms was formed in 90s
- Slope gradient varies from 1V:1.72H (lowest berm) to 1V:1H (highest berm)
- RL75m to RL110m.
- Geology: Granite formation.
- Slope movement was detected in Nov 2002 and obvious tension cracks were found at the lowest three berms.


SI & Instrumentation

- SI and instrumentation for failure investigations:
- 3 boreholes
- 22 Mackintosh Probes
- 2 inclinometers
- 3 observation wells

SI & Instrumentation Layout Plan



Slope Profile



Laboratory Test Results


- 8 C.I.U. tests
- 2 Multiple Reversal Direct Shear Box Tests
- Interpreted Moderate conservative soil parameters:

$$c'=2\text{kPa}, \phi'=31^\circ$$

Instrumentation Results

- Max lateral movement (IN. 1)
 - ~ 8mm with the depth of shear plane of about 7m tallies with stability analyses.

Slope Stability Analyses




Limit Equilibrium Method

Proposed Remedial Works

- Installation of Soil Nails (12m, 18m and 27m).
- Installation of horizontal drains.
- Repairing and re-construction of berm drains.

Proposed Remedial Works



Completed Soil Nailed Slope



Findings

Possible Causes of Failure

- The gradient of the cut slope is steep and is not stable in long term
- Slope strengthening works with installation of soil nails and subsoil drainage system have proven an effective solution to stabilise the distressed slope.

Fill Slope Failure at Salak Tinggi



Site Background

- Fill slope over a natural valley to form platform.
- Three berms slope : 20m height.
- Another three slopes on top of platform.
- Geology: Kenny Hill formation with interbedded sandstone and siltstone.
- Slope collapsed after heavy downpour.



Before Failure

After Failure



Site Observations

- The platform of pipeline was saturated.
- Concrete drains were clogged.
- Debris, tree trunks and vegetations indicated surface runoff overflowed the platform and traveled downslope to valley.
- Failed mass traveled more than 120m downhill along valley.

Site Observations



Site Observations

- Bedrock was observed at certain parts, indicating the failure resembles a slide along the bedrock surface.



SI and Laboratory Tests

- 3 boreholes were sunk.
- Sandy material – weathering from sandstone.
- CIU tests.
- Interpreted shear strength: $c' = 2 \text{ kPa}$, $\phi' = 32^\circ$.


Probable Causes of Failure

- Valley terrain.
- Steep fill slope gradient – steepest gradient of 1V:1H.
- Marginal FOS when groundwater level rises near to ground surface.
- Poor drainage system lead to saturation and erosion.

Remedial Works

- Fill embankment over valley.
- Fill embankment comprises of :
rock toe and seven berm slope (1V:2H).
- Provision of extensive subsoil drainage:
French drain and drainage blanket.
- Upgrading and construction of new drainage system.

Cross Section of Remedial Works



Failure Area

Construction of Fill
Embankment

Drainage
Blanket

Rock Toe

Rock Mattress

25 8 2003



After Completion of Construction Works



The End

Thank You